

Fig. 1

Figure 2 shows the effect of the amount of PVA on the gloss of the film. The gloss increases as the amount of PVA increases.




Fig. 2

Figure 3 is a line graph showing the release of a substance from a casting over time. The Y-axis represents Release (J/m²) and the X-axis represents the Number of Castings. Three data series are plotted: Invention (diamonds), Improper Cure (squares), and Control (triangles). The Invention series shows a steady increase in release from 20 J/m² at the 1st casting to 55 J/m² at the 5th casting. The Improper Cure series shows a steady increase from 40 J/m² at the 1st casting to 55 J/m² at the 5th casting. The Control series shows a steady increase from 30 J/m² at the 1st casting to 55 J/m² at the 5th casting.




Fig. 3